

After installation, DC Power should be measured on the Active Amplifier after the Voltage Regulator to make sure that it is close to +12vdc for best operation of the amplifier.